





M5272C3 Revision 2.2 Product Deviation

The M5272C3 User's Manual Rev 1.4 supplied in this kit is outdated. The following corrections should be applied:

- The "Limited Warranty" (first page) is not valid. Please refer to the separate Warranty Card, WNTYCARD1YMOT/D, for warranty information.
- The "M5272C3 Jumper Setup" section is incorrect for Revision 2.2 of the M5272C3. Please refer to the silk-screen on the secondary side of the M5272C3 evaluation board for the correct table.
- The Revision 2.2 M5272C3 is populated with a 16MB SDRAM. The manual states that a 4MB SDRAM is used. Therefore, the memory map on page 3-5 (table 3-1) should show the SDRAM address range as "0x00000000 to 0x00FFFFFF".
- "Appendix B PAL Equations" has been updated. Please refer to the M5272C3 web site for the updated file.
- The Schematics shown (Appendix C) are for Revision 1.4 of the M5272C3. Revision 2.2 schematics can be found on the M5272C3 web site.
- The BOM (Appendix D) is for Revision 1.4 of the M5272C3. The BOM for Revision 2.2 can be found on the M5272C3 web site.

To access the M5272C3 web site:

- Start at http://www.mot.com/coldfire
- From the selection box in the upper left corner, choose "Products → 68K/ColdFire Development Tools"
- Click "M5272C3" from the list of development systems